Because the chip is out of production, cube baby has different hardware, and now it needs different firmware to match it.

So after you mistakenly upgrade, you need to upgrade the firmware of the matching hardware so that your machine can be used normally. You can choose one of the three programs in the cloud to upgrade until your product can be used normally.