XLR - XLR

Pin 2   - Pin 2 (Hot)
Pin 3   - Pin 3 (Cold)
Pin 1   - Pin 1 (Shield)

Female Plug

Male Plug

Jack output (balanced) - XLR input

Tip   - Pin 2 (Hot)
Ring   - Pin 3 (Cold)
Sleeve   - Pin 1 (Shield)

TRS (Stereo) Jack

Male Plug

Jack output (unbalanced) - XLR input

Tip   - Pin 2 (Signal)
Sleeve   - Pin 3 (Shield)
Sleeve   - Pin 1 (Shield)

(Mono) Jack

Male Plug

XLR Plugs seen from solder side

XLR output - Jack input   (balanced)

Pin 2   - Tip (Hot)
Pin 3   - Ring (Cold)
Pin 1   - Sleeve (Shield)

Female Plug

TRS (Stereo) Jack

XLR output - Jack input   (unbalanced)

Pin 2   - Tip (Signal)
Pin 3   - Sleeve (Shield)
Pin 1   - Sleeve (Shield)

Female Plug

(Mono) Jack

XLR output - Jack input   (unbalanced) for P2 / DBMAX / D22 / 2290 / 1140 / 2240

Pin 2   - Tip (Signal)
Pin 3   - No Connection
Pin 1   - Sleeve (Shield)

Female Plug

TRS (Stereo) Jack

XLR Plugs seen from solder side